Contractor Name	Job Order Number R	Request Date Act	ctual Completion Date Actual Completion	n Time (if ap Urgency Description	Job Trade	Brief Description	Ins/Recharge	Full Works Description
UALITY GAS	122442	13/06/2012	13/06/2012	15:12:00 EMERGENCY	G	Leak at the boiler		Leak at the boiler
								Remove wardrobe doors from outside flat door as per xxxx - NOT TO BE
yde Coast Cleaning Contractors	122822	04/07/2012	05/07/2012 0:00:00	ROUTINE	W	Remove wardrobe doors from outside flat door as per xxxx - NOT TO BE RECHARGED		RECHARGED
reenock Relay Signals Limited	122827	04/07/2012	19/07/2012	17:00:00 ROUTINE	ſ	relocate existing bt point so tenant can use it		relocate existing bt point so tenant can use it
eter Nicol	122895	09/07/2012	10/07/2012 0:00:00	URGENT	P	reseal bath		reseal bath
				URGENT	r D			
F Watters	122896	09/07/2012	11/07/2012 0:00:00		В	carry out plaster repair to hall cupboard		carry out plaster repair to hall cupboard
AUL COUPER JOINERY LIMITED	122897	17/07/2012	17/07/2012 0:00:00	URGENT	J	fit dado rail in bedroom to match existing- Howdens range		fit dado rail in bedroom to match existing- Howdens range
S Joinery	123094	09/07/2012	17/07/2012 0:00:00	ROUTINE	J	please box in bath		please box in bath
UALITY GAS	123099	17/07/2012	19/07/2012 0:00:00	URGENT	G	Please box in heating pipes in hall way cupboard	R - Job has to be Re-charged	Please box in heating pipes in hall way cupboard
						Following AGS - Bonding greater than 600 mm from meter. Please check and rectify as		Following AGS - Bonding greater than 600 mm from meter. Please check
alliday Contract Services Limited	123848	22/08/2012	05/09/2012 0:00:00	ROUTINE	E	required.		rectify as required.
CG (SCOTLAND) LIMITED	124120	28/08/2012	14/01/2012 0:00:00	Major Repairs 2	C1	kitchen installation 12-13		kitchen installation 12-13
/ATES GROUP LIMITED	124180	30/08/2012	14/01/2012 0:00:00	Major Repairs 2	В	new heating installation 12-13		new heating installation 12-13
ISTURBANCE PAYMENTS					=	•		•
	124965	01/10/2012	09/10/2012 0:00:00	Cyclical 2	DIST	Disturbance payment 12/13		Disturbance payment 12/13
n Stewart Joiner and Glazier	126042	06/11/2012	20/11/2012 0:00:00	ROUTINE	J	check all windows in flat and reseal as required		check all windows in flat and reseal as required
UALITY GAS	126059	07/11/2012	20/11/2012 0:00:00	ROUTINE	Р	please repair taps in bathroom		please repair dripping taps in bathroom
S Joinery	129289	25/03/2013	26/03/2013 0:00:00	ROUTINE	J	Draughts from LR windows		Draughts from LR windows
eter Nicol	131691	20/06/2013	21/06/2013 0:00:00	ROUTINE	P	cold water tap in bathroom is very stiff		cold water tap in bathroom is very stiff
egency Doors & Stairs (Scotland) Ltd	131692	20/06/2013	03/07/2013 0:00:00	ROUTINE	J	Please secure all window handles and repair kitchen floor		Please secure all window handles and repair kitchen floor
/ATES GROUP LIMITED	131708	21/06/2013	22/06/2013 0:00:00	URGENT	DEF	HW too hot - problem with pressure on boiler		HW too hot - problem with pressure on boiler
AUL COUPER JOINERY LIMITED	136540	23/12/2013	23/12/2013	13:04:00 EMERGENCY		Please check for water ingress from windows		Please check for water ingress from windows
EORGE COOKE	137596		07/02/2014 0:00:00	ROUTINE	P	check and repair leak under sink		•
		06/02/2014	. , . ,		-			check and repair leak under sink
AMES FREW LTD	137671	10/02/2014	10/02/2014	16:38:00 EMERGENCY	G	no heating or hot water		please repair cause of no heating or hot water
EORGE COOKE	137672	10/02/2014	10/02/2014	16:30:00 EMERGENCY	P	hot tap on bath will not shut off		please repair or replace hot tap to bath
S Joinery	137861	17/02/2014	25/02/2014 0:00:00	ROUTINE	J	Please check and repair kitchen cupboard doors - T reports all have dropped		Please check and repair kitchen cupboard doors - T reports all have drop
AMES FREW LTD	140662	06/06/2014	06/06/2014 9:50:00	Gas Remedial Work	G	Replace conveyor as per service		Replace conveyor as per service
		, , , , , , , , ,	, , , , , , , , , , , , , , , , , , , ,			take out washing machine and secure floorboards fit plywood pad to floor below washing		take out washing machine and secure floorboards fit plywood pad to flo
COTT GAGE CONSTRUCTION SERVICES	143442	13/10/2014	15/10/2014	11:00:00 URGENT		machine refit machine and check for level		below washing machine refit machine and check for level
eter Nicol	143780	27/10/2014	28/10/2014 9:00:00	RIGHT TO REPAIR 1	P	Check WC and Kitchen sink - T reports is blocked		Check WC and Kitchen sink - T reports is blocked
			· ·			·		·
S Joinery	146997	05/02/2015	19/02/2015 0:00:00	ROUTINE	J	please rehang kitchen unit door		please rehang kitchen unit door
n Stewart Joiner and Glazier	146998	05/02/2015	18/02/2015 0:00:00	ROUTINE	J	rake out mastic around both bedroom windows and remastic		rake out mastic around both bedroom windows and remastic
AUL COUPER JOINERY LIMITED	147878	04/03/2015	09/03/2015 0:00:00	URGENT	J	(1) Resecure handles on all windows (2) resecureall doors on kitchen units		(1) Resecure handles on all windows (2) resecure all doors on kitchen un
raig Shearer Aerial & Satellite Services	147879	04/03/2015	09/03/2015 0:00:00	URGENT	С	No audio at D/E unable to allow entry		No audio at D/E unable to allow entry
eter Nicol	151412	03/07/2015	03/07/2015	10:00:00 EMERGENCY	Р	CALL-OUT choked toilet		CALL-OUT choked toilet
COTT GAGE CONSTRUCTION SERVICES	151933	04/08/2015	14/08/2015 0:00:00	ROUTINE	Н	Make good hole above extractor fan in bathroom		Make good hole above extractor fan in bathroom
COTT GAGE CONSTRUCTION SERVICES	151555	04/00/2013	14/00/2015 0.00.00	NOOTINE		Check gaskets and seals on all windows and replace as required / realign kitchen base unit		Check gaskets and seals on all windows and replace as required / realign
Character Indiana and Classica	455444	04/42/2045	10/12/2015 0:00:00	POLITING				
an Stewart Joiner and Glazier	155111	01/12/2015	10/12/2015 0:00:00	ROUTINE	J	door		kitchen base unit door
eter Nicol	156363	15/01/2016	22/01/2016 0:00:00	ROUTINE	Р	Check all bathroom taps and repair/replace as required		Check all bathroom taps and repair/replace as required
AMES FREW LTD	180189	29/08/2018	29/08/2018 0:00:00	Urgent 2 day repair	G	Conf: no ch/hw		Conf: no ch/hw
AMES FREW LTD	180804	21/09/2018	21/09/2018 0:00:00	Urgent 2 day repair	G	Conf: NO CH/HW		Conf: NO CH/HW
								Client Inspection:Undertake client inspection and testing etc. on external
								joinery and report to Client Representative (any repairs required to be
IOVUS Property Solutions Ltd	181485	12/10/2018	15/10/2018 9:30:00	ROUTINE	J	WINDOW:OVERHAUL SASH NO		ordered must be instructed by Client Representative).
io rob rroperty defaulteris alta	101.03	22/10/2010	13/10/2010 3.00.00	HOOTHIE	-			
								Regions all lower D/C units in livingroom and both hadrooms with K type
								Reglaze all lower D/G units in livingroom and both bedrooms with K type
						Reglaze all lower D/G units in livingroom and both bedrooms with K type energy efficient		
								energy efficient glass. Ensure all cockspur handles are full secure and all
n Stewart Joiner and Glazier	184727	13/02/2019	26/02/2019 0:00:00	ROUTINE	J	glass. Fix flooring at w/m space and fit ply pad also		gaskets are in place. Fix flooring at w/m space and fit ply pad also
n Stewart Joiner and Glazier	184727	13/02/2019	26/02/2019 0:00:00	ROUTINE	J			
	184727 184732	13/02/2019	26/02/2019 0:00:00 08/03/2019 0:00:00	ROUTINE	J A	glass. Fix flooring at w/m space and fit ply pad also		gaskets are in place. Fix flooring at w/m space and fit ply pad also
nccol					J A G	glass. Fix flooring at w/m space and fit ply pad also Stain block over damp patch and emulsion livingroom ceiling following recurring roof leak		gaskets are in place. Fix flooring at w/m space and fit ply pad also Stain block over damp patch and emulsion livingroom ceiling following
nccol	184732	13/02/2019	08/03/2019 0:00:00	ROUTINE		glass. Fix flooring at w/m space and fit ply pad also Stain block over damp patch and emulsion livingroom ceiling following recurring roof leak (now repaired)		gaskets are in place. Fix flooring at w/m space and fit ply pad also Stain block over damp patch and emulsion livingroom ceiling following recurring roof leak (now repaired) no heating in property
nccol AMES FREW LTD	184732 185914	13/02/2019 28/03/2019	08/03/2019 0:00:00 28/03/2019 0:00:00	ROUTINE RIGHT TO REPAIR 1		glass. Fix flooring at w/m space and fit ply pad also Stain block over damp patch and emulsion livingroom ceiling following recurring roof leak (now repaired) no heating in property Fit UPVC overclad cills to all windows - replace defective cockspur handle on right hand		gaskets are in place. Fix flooring at w/m space and fit ply pad also Stain block over damp patch and emulsion livingroom ceiling following recurring roof leak (now repaired) no heating in property Fit UPVC overclad cills to all windows - replace defective cockspur handle
nccol AMES FREW LTD on Stewart Joiner and Glazier	184732 185914 186259	13/02/2019 28/03/2019 09/04/2019	08/03/2019 0:00:00 28/03/2019 0:00:00 17/04/2019 0:00:00	ROUTINE RIGHT TO REPAIR 1 ROUTINE	G	glass. Fix flooring at w/m space and fit ply pad also Stain block over damp patch and emulsion livingroom ceiling following recurring roof leak (now repaired) no heating in property Fit UPVC overclad cills to all windows - replace defective cockspur handle on right hand window in livingroom - check all other handles.		gaskets are in place. Fix flooring at w/m space and fit ply pad also Stain block over damp patch and emulsion livingroom ceiling following recurring roof leak (now repaired) no heating in property Fit UPVC overclad cills to all windows - replace defective cockspur handle right hand window in livingroom - check all other handles.
nccol AMES FREW LTD In Stewart Joiner and Glazier AMES FREW LTD	184732 185914 186259 186277	13/02/2019 28/03/2019 09/04/2019 28/03/2019	08/03/2019 0:00:00 28/03/2019 0:00:00 17/04/2019 0:00:00 05/04/2019 0:00:00	ROUTINE RIGHT TO REPAIR 1 ROUTINE ROUTINE	G G	glass. Fix flooring at w/m space and fit ply pad also Stain block over damp patch and emulsion livingroom ceiling following recurring roof leak (now repaired) no heating in property Fit UPVC overclad cills to all windows - replace defective cockspur handle on right hand window in livingroom - check all other handles. Further work req - replace PCB		gaskets are in place. Fix flooring at w/m space and fit ply pad also Stain block over damp patch and emulsion livingroom ceiling following recurring roof leak (now repaired) no heating in property Fit UPVC overclad cills to all windows - replace defective cockspur handle right hand window in livingroom - check all other handles. Further work req - replace PCB
nccol AMES FREW LTD an Stewart Joiner and Glazier AMES FREW LTD	184732 185914 186259	13/02/2019 28/03/2019 09/04/2019	08/03/2019 0:00:00 28/03/2019 0:00:00 17/04/2019 0:00:00	ROUTINE RIGHT TO REPAIR 1 ROUTINE	G	glass. Fix flooring at w/m space and fit ply pad also Stain block over damp patch and emulsion livingroom ceiling following recurring roof leak (now repaired) no heating in property Fit UPVC overclad cills to all windows - replace defective cockspur handle on right hand window in livingroom - check all other handles.		gaskets are in place. Fix flooring at w/m space and fit ply pad also Stain block over damp patch and emulsion livingroom ceiling following recurring roof leak (now repaired) no heating in property Fit UPVC overclad cills to all windows - replace defective cockspur handle right hand window in livingroom - check all other handles.
nccol AMES FREW LTD an Stewart Joiner and Glazier AMES FREW LTD	184732 185914 186259 186277	13/02/2019 28/03/2019 09/04/2019 28/03/2019	08/03/2019 0:00:00 28/03/2019 0:00:00 17/04/2019 0:00:00 05/04/2019 0:00:00	ROUTINE RIGHT TO REPAIR 1 ROUTINE ROUTINE	G G	glass. Fix flooring at w/m space and fit ply pad also Stain block over damp patch and emulsion livingroom ceiling following recurring roof leak (now repaired) no heating in property Fit UPVC overclad cills to all windows - replace defective cockspur handle on right hand window in livingroom - check all other handles. Further work req - replace PCB		gaskets are in place. Fix flooring at w/m space and fit ply pad also Stain block over damp patch and emulsion livingroom ceiling following recurring roof leak (now repaired) no heating in property Fit UPVC overclad cills to all windows - replace defective cockspur handle right hand window in livingroom - check all other handles. Further work req - replace PCB Confirmation: Fire Detection Upgrade carried out at AGS
nccol AMES FREW LTD on Stewart Joiner and Glazier AMES FREW LTD	184732 185914 186259 186277 188685	13/02/2019 28/03/2019 09/04/2019 28/03/2019 09/07/2019	08/03/2019 0:00:00 28/03/2019 0:00:00 17/04/2019 0:00:00 05/04/2019 0:00:00 09/07/2019 0:00:00	ROUTINE RIGHT TO REPAIR 1 ROUTINE ROUTINE ROUTINE	G G	glass. Fix flooring at w/m space and fit ply pad also Stain block over damp patch and emulsion livingroom ceiling following recurring roof leak (now repaired) no heating in property Fit UPVC overclad cills to all windows - replace defective cockspur handle on right hand window in livingroom - check all other handles. Further work req - replace PCB Confirmation : Fire Detection Upgrade carried outat AGS		gaskets are in place. Fix flooring at w/m space and fit ply pad also Stain block over damp patch and emulsion livingroom ceiling following recurring roof leak (now repaired) no heating in property Fit UPVC overclad cills to all windows - replace defective cockspur handle right hand window in livingroom - check all other handles. Further work req - replace PCB Confirmation: Fire Detection Upgrade carried out at AGS Confirmation call out - OOH Callout ORP20740 - water coming in through
nccol AMES FREW LTD an Stewart Joiner and Glazier AMES FREW LTD AMES FREW LTD	184732 185914 186259 186277	13/02/2019 28/03/2019 09/04/2019 28/03/2019	08/03/2019 0:00:00 28/03/2019 0:00:00 17/04/2019 0:00:00 05/04/2019 0:00:00	ROUTINE RIGHT TO REPAIR 1 ROUTINE ROUTINE	G G	glass. Fix flooring at w/m space and fit ply pad also Stain block over damp patch and emulsion livingroom ceiling following recurring roof leak (now repaired) no heating in property Fit UPVC overclad cills to all windows - replace defective cockspur handle on right hand window in livingroom - check all other handles. Further work req - replace PCB		gaskets are in place. Fix flooring at w/m space and fit ply pad also Stain block over damp patch and emulsion livingroom ceiling following recurring roof leak (now repaired) no heating in property Fit UPVC overclad cills to all windows - replace defective cockspur handle right hand window in livingroom - check all other handles. Further work req - replace PCB Confirmation: Fire Detection Upgrade carried out at AGS Confirmation call out - OOH Callout ORP20740 - water coming in through
an Stewart Joiner and Glazier nccol AMES FREW LTD an Stewart Joiner and Glazier AMES FREW LTD AMES FREW LTD MPS Housing Ltd Northern (Mitie)	184732 185914 186259 186277 188685	13/02/2019 28/03/2019 09/04/2019 28/03/2019 09/07/2019	08/03/2019 0:00:00 28/03/2019 0:00:00 17/04/2019 0:00:00 05/04/2019 0:00:00 09/07/2019 0:00:00	ROUTINE RIGHT TO REPAIR 1 ROUTINE ROUTINE ROUTINE	G J G G	glass. Fix flooring at w/m space and fit ply pad also Stain block over damp patch and emulsion livingroom ceiling following recurring roof leak (now repaired) no heating in property Fit UPVC overclad cills to all windows - replace defective cockspur handle on right hand window in livingroom - check all other handles. Further work req - replace PCB Confirmation : Fire Detection Upgrade carried outat AGS		gaskets are in place. Fix flooring at w/m space and fit ply pad also Stain block over damp patch and emulsion livingroom ceiling following recurring roof leak (now repaired) no heating in property Fit UPVC overclad cills to all windows - replace defective cockspur handle right hand window in livingroom - check all other handles. Further work req - replace PCB
AMES FREW LTD an Stewart Joiner and Glazier AMES FREW LTD AMES FREW LTD MPS Housing Ltd Northern (Mitie)	184732 185914 186259 186277 188685	13/02/2019 28/03/2019 09/04/2019 28/03/2019 09/07/2019	08/03/2019 0:00:00 28/03/2019 0:00:00 17/04/2019 0:00:00 05/04/2019 0:00:00 09/07/2019 0:00:00	ROUTINE RIGHT TO REPAIR 1 ROUTINE ROUTINE ROUTINE ROUTINE 22:00:00 EMERGENCY	G J G G	glass. Fix flooring at w/m space and fit ply pad also Stain block over damp patch and emulsion livingroom ceiling following recurring roof leak (now repaired) no heating in property Fit UPVC overclad cills to all windows - replace defective cockspur handle on right hand window in livingroom - check all other handles. Further work req - replace PCB Confirmation : Fire Detection Upgrade carried outat AGS OOH call out - water ingress Out of Hours - General Building Craftsperson HR		gaskets are in place. Fix flooring at w/m space and fit ply pad also Stain block over damp patch and emulsion livingroom ceiling following recurring roof leak (now repaired) no heating in property Fit UPVC overclad cills to all windows - replace defective cockspur handle right hand window in livingroom - check all other handles. Further work req - replace PCB Confirmation: Fire Detection Upgrade carried out at AGS Confirmation call out - OOH Callout ORP20740 - water coming in through bedroom window from gutters Out of Hours - General Building Craftsper
AMES FREW LTD an Stewart Joiner and Glazier AMES FREW LTD AMES FREW LTD MPS Housing Ltd Northern (Mitie)	184732 185914 186259 186277 188685	13/02/2019 28/03/2019 09/04/2019 28/03/2019 09/07/2019 18/12/2019	08/03/2019 0:00:00 28/03/2019 0:00:00 17/04/2019 0:00:00 05/04/2019 0:00:00 09/07/2019 0:00:00	ROUTINE RIGHT TO REPAIR 1 ROUTINE ROUTINE ROUTINE	G J G G	glass. Fix flooring at w/m space and fit ply pad also Stain block over damp patch and emulsion livingroom ceiling following recurring roof leak (now repaired) no heating in property Fit UPVC overclad cills to all windows - replace defective cockspur handle on right hand window in livingroom - check all other handles. Further work req - replace PCB Confirmation : Fire Detection Upgrade carried outat AGS		gaskets are in place. Fix flooring at w/m space and fit ply pad also Stain block over damp patch and emulsion livingroom ceiling following recurring roof leak (now repaired) no heating in property Fit UPVC overclad cills to all windows - replace defective cockspur handle right hand window in livingroom - check all other handles. Further work req - replace PCB Confirmation : Fire Detection Upgrade carried out at AGS Confirmation call out - OOH Callout ORP20740 - water coming in through bedroom window from gutters Out of Hours - General Building Craftsper Water coming in through top of bedroom window. OOH call out enginee reported that window needed to be resealed.
nccol AMES FREW LTD an Stewart Joiner and Glazier AMES FREW LTD AMES FREW LTD	184732 185914 186259 186277 188685	13/02/2019 28/03/2019 09/04/2019 28/03/2019 09/07/2019 18/12/2019	08/03/2019 0:00:00 28/03/2019 0:00:00 17/04/2019 0:00:00 05/04/2019 0:00:00 09/07/2019 0:00:00	ROUTINE RIGHT TO REPAIR 1 ROUTINE ROUTINE ROUTINE ROUTINE 22:00:00 EMERGENCY	G J G G	glass. Fix flooring at w/m space and fit ply pad also Stain block over damp patch and emulsion livingroom ceiling following recurring roof leak (now repaired) no heating in property Fit UPVC overclad cills to all windows - replace defective cockspur handle on right hand window in livingroom - check all other handles. Further work req - replace PCB Confirmation : Fire Detection Upgrade carried outat AGS OOH call out - water ingress Out of Hours - General Building Craftsperson HR		gaskets are in place. Fix flooring at w/m space and fit ply pad also Stain block over damp patch and emulsion livingroom ceiling following recurring roof leak (now repaired) no heating in property Fit UPVC overclad cills to all windows - replace defective cockspur handle right hand window in livingroom - check all other handles. Further work req - replace PCB Confirmation : Fire Detection Upgrade carried out at AGS Confirmation call out - OOH Callout ORP20740 - water coming in through bedroom window from gutters Out of Hours - General Building Craftsper Water coming in through top of bedroom window. OOH call out engineer reported that window needed to be resealed. Apply mould wash to bedroom walls - as per MD & MV Surfaces:Prepare
an Stewart Joiner and Glazier AMES FREW LTD AMES FREW LTD AMES FREW LTD AMES FREW LTD	184732 185914 186259 186277 188685	13/02/2019 28/03/2019 09/04/2019 28/03/2019 09/07/2019 18/12/2019	08/03/2019 0:00:00 28/03/2019 0:00:00 17/04/2019 0:00:00 05/04/2019 0:00:00 09/07/2019 0:00:00	ROUTINE RIGHT TO REPAIR 1 ROUTINE ROUTINE ROUTINE ROUTINE 22:00:00 EMERGENCY	G J G G	glass. Fix flooring at w/m space and fit ply pad also Stain block over damp patch and emulsion livingroom ceiling following recurring roof leak (now repaired) no heating in property Fit UPVC overclad cills to all windows - replace defective cockspur handle on right hand window in livingroom - check all other handles. Further work req - replace PCB Confirmation : Fire Detection Upgrade carried outat AGS OOH call out - water ingress Out of Hours - General Building Craftsperson HR		gaskets are in place. Fix flooring at w/m space and fit ply pad also Stain block over damp patch and emulsion livingroom ceiling following recurring roof leak (now repaired) no heating in property Fit UPVC overclad cills to all windows - replace defective cockspur handle right hand window in livingroom - check all other handles. Further work req - replace PCB Confirmation : Fire Detection Upgrade carried out at AGS Confirmation call out - OOH Callout ORP20740 - water coming in through bedroom window from gutters Out of Hours - General Building Craftsper Water coming in through top of bedroom window. OOH call out enginee reported that window needed to be resealed. Apply mould wash to bedroom walls - as per MD & MV Surfaces:Prepare wash down with RLT Bactdet solution prepare and apply one coat RLT
ccol IMES FREW LTD INSTEWART Joiner and Glazier IMES FREW LTD (Mitie) INSTEWART Joiner and Glazier	184732 185914 186259 186277 188685 193584	13/02/2019 28/03/2019 09/04/2019 28/03/2019 09/07/2019 18/12/2019	08/03/2019 0:00:00 28/03/2019 0:00:00 17/04/2019 0:00:00 05/04/2019 0:00:00 09/07/2019 0:00:00 18/12/2019 19/12/2019 0:00:00	ROUTINE RIGHT TO REPAIR 1 ROUTINE ROUTINE ROUTINE 22:00:00 EMERGENCY Urgent 2 day repair	G J G G	glass. Fix flooring at w/m space and fit ply pad also Stain block over damp patch and emulsion livingroom ceiling following recurring roof leak (now repaired) no heating in property Fit UPVC overclad cills to all windows - replace defective cockspur handle on right hand window in livingroom - check all other handles. Further work req - replace PCB Confirmation : Fire Detection Upgrade carried outat AGS OOH call out - water ingress Out of Hours - General Building Craftsperson HR Water coming in through top of bedroom window.		gaskets are in place. Fix flooring at w/m space and fit ply pad also Stain block over damp patch and emulsion livingroom ceiling following recurring roof leak (now repaired) no heating in property Fit UPVC overclad cills to all windows - replace defective cockspur handle right hand window in livingroom - check all other handles. Further work req - replace PCB Confirmation : Fire Detection Upgrade carried out at AGS Confirmation call out - OOH Callout ORP20740 - water coming in through bedroom window from gutters Out of Hours - General Building Craftsper Water coming in through top of bedroom window. OOH call out enginee reported that window needed to be resealed. Apply mould wash to bedroom walls - as per MD & MV Surfaces:Prepare wash down with RLT Bactdet solution prepare and apply one coat RL Halophen solution to walls or ceilings in accordance with manufacturers
n Stewart Joiner and Glazier MMES FREW LTD IN Stewart Joiner and Glazier MMES FREW LTD IPS Housing Ltd Northern (Mitie) In Stewart Joiner and Glazier	184732 185914 186259 186277 188685	13/02/2019 28/03/2019 09/04/2019 28/03/2019 09/07/2019 18/12/2019	08/03/2019 0:00:00 28/03/2019 0:00:00 17/04/2019 0:00:00 05/04/2019 0:00:00 09/07/2019 0:00:00	ROUTINE RIGHT TO REPAIR 1 ROUTINE ROUTINE ROUTINE ROUTINE 22:00:00 EMERGENCY	G J G G	glass. Fix flooring at w/m space and fit ply pad also Stain block over damp patch and emulsion livingroom ceiling following recurring roof leak (now repaired) no heating in property Fit UPVC overclad cills to all windows - replace defective cockspur handle on right hand window in livingroom - check all other handles. Further work req - replace PCB Confirmation : Fire Detection Upgrade carried outat AGS OOH call out - water ingress Out of Hours - General Building Craftsperson HR		gaskets are in place. Fix flooring at w/m space and fit ply pad also Stain block over damp patch and emulsion livingroom ceiling following recurring roof leak (now repaired) no heating in property Fit UPVC overclad cills to all windows - replace defective cockspur handle right hand window in livingroom - check all other handles. Further work req - replace PCB Confirmation: Fire Detection Upgrade carried out at AGS Confirmation call out - OOH Callout ORP20740 - water coming in through bedroom window from gutters Out of Hours - General Building Craftsper Water coming in through top of bedroom window. OOH call out enginee reported that window needed to be resealed. Apply mould wash to bedroom walls - as per MD & MV Surfaces:Prepare wash down with RLT Bactdet solution prepare and apply one coat RLT Halophen solution to walls or ceilings in accordance with manufacturers data sheet 2 coats of Biocheck matt.
n Stewart Joiner and Glazier MMES FREW LTD MMES FREW LTD MMES FREW LTD MPS Housing Ltd Northern (Mitie) IPS Housing Ltd Northern (Mitie)	184732 185914 186259 186277 188685 193584 193586	13/02/2019 28/03/2019 09/04/2019 28/03/2019 09/07/2019 18/12/2019 19/12/2019	08/03/2019 0:00:00 28/03/2019 0:00:00 17/04/2019 0:00:00 05/04/2019 0:00:00 09/07/2019 0:00:00 18/12/2019 19/12/2019 0:00:00	ROUTINE RIGHT TO REPAIR 1 ROUTINE ROUTINE ROUTINE 22:00:00 EMERGENCY Urgent 2 day repair 13:30:00 ROUTINE	G J G G J	glass. Fix flooring at w/m space and fit ply pad also Stain block over damp patch and emulsion livingroom ceiling following recurring roof leak (now repaired) no heating in property Fit UPVC overclad cills to all windows - replace defective cockspur handle on right hand window in livingroom - check all other handles. Further work req - replace PCB Confirmation : Fire Detection Upgrade carried outat AGS OOH call out - water ingress Out of Hours - General Building Craftsperson HR Water coming in through top of bedroom window.		gaskets are in place. Fix flooring at w/m space and fit ply pad also Stain block over damp patch and emulsion livingroom ceiling following recurring roof leak (now repaired) no heating in property Fit UPVC overclad cills to all windows - replace defective cockspur handle right hand window in livingroom - check all other handles. Further work req - replace PCB Confirmation: Fire Detection Upgrade carried out at AGS Confirmation call out - OOH Callout ORP20740 - water coming in through bedroom window from gutters Out of Hours - General Building Craftsper Water coming in through top of bedroom window. OOH call out enginee reported that window needed to be resealed. Apply mould wash to bedroom walls - as per MD & MV Surfaces:Prepare wash down with RLT Bactdet solution prepare and apply one coat RLT Halophen solution to walls or ceilings in accordance with manufacturers data sheet 2 coats of Biocheck matt. Fan:Overhaul any kind of domestic extractor fan dismantle and reassen
n Stewart Joiner and Glazier MMES FREW LTD MMES FREW LTD MMES FREW LTD MPS Housing Ltd Northern (Mitie) IPS Housing Ltd Northern (Mitie)	184732 185914 186259 186277 188685 193584	13/02/2019 28/03/2019 09/04/2019 28/03/2019 09/07/2019 18/12/2019	08/03/2019 0:00:00 28/03/2019 0:00:00 17/04/2019 0:00:00 05/04/2019 0:00:00 09/07/2019 0:00:00 18/12/2019 19/12/2019 0:00:00	ROUTINE RIGHT TO REPAIR 1 ROUTINE ROUTINE ROUTINE 22:00:00 EMERGENCY Urgent 2 day repair	G J G G	glass. Fix flooring at w/m space and fit ply pad also Stain block over damp patch and emulsion livingroom ceiling following recurring roof leak (now repaired) no heating in property Fit UPVC overclad cills to all windows - replace defective cockspur handle on right hand window in livingroom - check all other handles. Further work req - replace PCB Confirmation : Fire Detection Upgrade carried outat AGS OOH call out - water ingress Out of Hours - General Building Craftsperson HR Water coming in through top of bedroom window.		gaskets are in place. Fix flooring at w/m space and fit ply pad also Stain block over damp patch and emulsion livingroom ceiling following recurring roof leak (now repaired) no heating in property Fit UPVC overclad cills to all windows - replace defective cockspur handle right hand window in livingroom - check all other handles. Further work req - replace PCB Confirmation: Fire Detection Upgrade carried out at AGS Confirmation call out - OOH Callout ORP20740 - water coming in through bedroom window from gutters Out of Hours - General Building Craftsper Water coming in through top of bedroom window. OOH call out enginee reported that window needed to be resealed. Apply mould wash to bedroom walls - as per MD & MV Surfaces:Prepare wash down with RLT Bactdet solution prepare and apply one coat RLT Halophen solution to walls or ceilings in accordance with manufacturers data sheet 2 coats of Biocheck matt. Fan:Overhaul any kind of domestic extractor fan dismantle and reassen clean and oil test and leave in working order.
n Stewart Joiner and Glazier MMES FREW LTD MMES FREW LTD MMES FREW LTD MPS Housing Ltd Northern (Mitie) IPS Housing Ltd Northern (Mitie)	184732 185914 186259 186277 188685 193584 193586	13/02/2019 28/03/2019 09/04/2019 28/03/2019 09/07/2019 18/12/2019 19/12/2019	08/03/2019 0:00:00 28/03/2019 0:00:00 17/04/2019 0:00:00 05/04/2019 0:00:00 09/07/2019 0:00:00 18/12/2019 19/12/2019 0:00:00	ROUTINE RIGHT TO REPAIR 1 ROUTINE ROUTINE ROUTINE 22:00:00 EMERGENCY Urgent 2 day repair 13:30:00 ROUTINE	G J G G J	glass. Fix flooring at w/m space and fit ply pad also Stain block over damp patch and emulsion livingroom ceiling following recurring roof leak (now repaired) no heating in property Fit UPVC overclad cills to all windows - replace defective cockspur handle on right hand window in livingroom - check all other handles. Further work req - replace PCB Confirmation : Fire Detection Upgrade carried outat AGS OOH call out - water ingress Out of Hours - General Building Craftsperson HR Water coming in through top of bedroom window.		gaskets are in place. Fix flooring at w/m space and fit ply pad also Stain block over damp patch and emulsion livingroom ceiling following recurring roof leak (now repaired) no heating in property Fit UPVC overclad cills to all windows - replace defective cockspur handle right hand window in livingroom - check all other handles. Further work req - replace PCB Confirmation: Fire Detection Upgrade carried out at AGS Confirmation call out - OOH Callout ORP20740 - water coming in through bedroom window from gutters Out of Hours - General Building Craftsper Water coming in through top of bedroom window. OOH call out engineer reported that window needed to be resealed. Apply mould wash to bedroom walls - as per MD & MV Surfaces:Prepare wash down with RLT Bactdet solution prepare and apply one coat RLT Halophen solution to walls or ceilings in accordance with manufacturers data sheet 2 coats of Biocheck matt. Fan:Overhaul any kind of domestic extractor fan dismantle and reassen
AMES FREW LTD In Stewart Joiner and Glazier AMES FREW LTD AMES FREW LTD AMES FREW LTD IPS Housing Ltd Northern (Mitie) IPS Housing Ltd Northern (Mitie) IPS Housing Ltd Northern (Mitie)	184732 185914 186259 186277 188685 193584 193586	13/02/2019 28/03/2019 09/04/2019 28/03/2019 09/07/2019 18/12/2019 19/12/2019 19/12/2019	08/03/2019 0:00:00 28/03/2019 0:00:00 17/04/2019 0:00:00 05/04/2019 0:00:00 09/07/2019 0:00:00 18/12/2019 19/12/2019 0:00:00	ROUTINE RIGHT TO REPAIR 1 ROUTINE ROUTINE ROUTINE 22:00:00 EMERGENCY Urgent 2 day repair 13:30:00 ROUTINE	G J G G J	glass. Fix flooring at w/m space and fit ply pad also Stain block over damp patch and emulsion livingroom ceiling following recurring roof leak (now repaired) no heating in property Fit UPVC overclad cills to all windows - replace defective cockspur handle on right hand window in livingroom - check all other handles. Further work req - replace PCB Confirmation : Fire Detection Upgrade carried outat AGS OOH call out - water ingress Out of Hours - General Building Craftsperson HR Water coming in through top of bedroom window. SURFACES:APPLY BACTDET AND HALOPHEN SM FAN:OVERHAUL DOMESTIC EXTRACT NO		gaskets are in place. Fix flooring at w/m space and fit ply pad also Stain block over damp patch and emulsion livingroom ceiling following recurring roof leak (now repaired) no heating in property Fit UPVC overclad cills to all windows - replace defective cockspur handle right hand window in livingroom - check all other handles. Further work req - replace PCB Confirmation: Fire Detection Upgrade carried out at AGS Confirmation call out - OOH Callout ORP20740 - water coming in through bedroom window from gutters Out of Hours - General Building Craftsper Water coming in through top of bedroom window. OOH call out engineer reported that window needed to be resealed. Apply mould wash to bedroom walls - as per MD & MV Surfaces:Prepar wash down with RLT Bactdet solution prepare and apply one coat RLT Halophen solution to walls or ceilings in accordance with manufacturers data sheet 2 coats of Biocheck matt. Fan:Overhaul any kind of domestic extractor fan dismantle and reassen clean and oil test and leave in working order.
In Stewart Joiner and Glazier INMES FREW LTD INMES FREW LTD INMES FREW LTD INMES FREW LTD INFS Housing Ltd Northern (Mitie)	184732 185914 186259 186277 188685 193584 193586	13/02/2019 28/03/2019 09/04/2019 28/03/2019 09/07/2019 18/12/2019 19/12/2019 19/12/2019 17/01/2020 24/03/2020	08/03/2019 0:00:00 28/03/2019 0:00:00 17/04/2019 0:00:00 05/04/2019 0:00:00 09/07/2019 0:00:00 18/12/2019 19/12/2019 0:00:00 08/01/2020 28/01/2020 9:31:00 06/04/2020 0:00:00	ROUTINE RIGHT TO REPAIR 1 ROUTINE ROUTINE ROUTINE 22:00:00 EMERGENCY Urgent 2 day repair 13:30:00 ROUTINE RIGHT TO REPAIR 7 ROUTINE	G J G B J A E	glass. Fix flooring at w/m space and fit ply pad also Stain block over damp patch and emulsion livingroom ceiling following recurring roof leak (now repaired) no heating in property Fit UPVC overclad cills to all windows - replace defective cockspur handle on right hand window in livingroom - check all other handles. Further work req - replace PCB Confirmation : Fire Detection Upgrade carried outat AGS OOH call out - water ingress Out of Hours - General Building Craftsperson HR Water coming in through top of bedroom window. SURFACES:APPLY BACTDET AND HALOPHEN SM FAN:OVERHAUL DOMESTIC EXTRACT NO Supply 9 double glazed units - installation line to follow after COVID-19 restrictions are removed		gaskets are in place. Fix flooring at w/m space and fit ply pad also Stain block over damp patch and emulsion livingroom ceiling following recurring roof leak (now repaired) no heating in property Fit UPVC overclad cills to all windows - replace defective cockspur handl right hand window in livingroom - check all other handles. Further work req - replace PCB Confirmation : Fire Detection Upgrade carried out at AGS Confirmation call out - OOH Callout ORP20740 - water coming in througl bedroom window from gutters Out of Hours - General Building Craftspel Water coming in through top of bedroom window. OOH call out enginee reported that window needed to be resealed. Apply mould wash to bedroom walls - as per MD & MV Surfaces:Prepar wash down with RLT Bactdet solution prepare and apply one coat RL Halophen solution to walls or ceilings in accordance with manufacturers data sheet 2 coats of Biocheck matt. Fan:Overhaul any kind of domestic extractor fan dismantle and reasser clean and oil test and leave in working order. Supply 9 double glazed units - installation line to follow after COVID-19 restrictions are removed
In Stewart Joiner and Glazier INMES FREW LTD INMES FREW LTD INMES FREW LTD INMES FREW LTD INFS Housing Ltd Northern (Mitie)	184732 185914 186259 186277 188685 193584 193586	13/02/2019 28/03/2019 09/04/2019 28/03/2019 09/07/2019 18/12/2019 19/12/2019 19/12/2019	08/03/2019 0:00:00 28/03/2019 0:00:00 17/04/2019 0:00:00 05/04/2019 0:00:00 09/07/2019 0:00:00 18/12/2019 19/12/2019 0:00:00 08/01/2020 28/01/2020 9:31:00	ROUTINE RIGHT TO REPAIR 1 ROUTINE ROUTINE ROUTINE 22:00:00 EMERGENCY Urgent 2 day repair 13:30:00 ROUTINE RIGHT TO REPAIR 7	G J G G J	glass. Fix flooring at w/m space and fit ply pad also Stain block over damp patch and emulsion livingroom ceiling following recurring roof leak (now repaired) no heating in property Fit UPVC overclad cills to all windows - replace defective cockspur handle on right hand window in livingroom - check all other handles. Further work req - replace PCB Confirmation : Fire Detection Upgrade carried outat AGS OOH call out - water ingress Out of Hours - General Building Craftsperson HR Water coming in through top of bedroom window. SURFACES:APPLY BACTDET AND HALOPHEN SM FAN:OVERHAUL DOMESTIC EXTRACT NO Supply 9 double glazed units - installation line to follow after COVID-19 restrictions are		gaskets are in place. Fix flooring at w/m space and fit ply pad also Stain block over damp patch and emulsion livingroom ceiling following recurring roof leak (now repaired) no heating in property Fit UPVC overclad cills to all windows - replace defective cockspur handl right hand window in livingroom - check all other handles. Further work req - replace PCB Confirmation : Fire Detection Upgrade carried out at AGS Confirmation call out - OOH Callout ORP20740 - water coming in through bedroom window from gutters Out of Hours - General Building Craftspei Water coming in through top of bedroom window. OOH call out engineer reported that window needed to be resealed. Apply mould wash to bedroom walls - as per MD & MV Surfaces:Prepar wash down with RLT Bactdet solution prepare and apply one coat RL Halophen solution to walls or ceilings in accordance with manufacturers data sheet 2 coats of Biocheck matt. Fan:Overhaul any kind of domestic extractor fan dismantle and reasser clean and oil test and leave in working order. Supply 9 double glazed units - installation line to follow after COVID-19 restrictions are removed No CH/HW
an Stewart Joiner and Glazier AMES FREW LTD	184732 185914 186259 186277 188685 193584 193586 193597 194516 196454 196498	13/02/2019 28/03/2019 09/04/2019 28/03/2019 09/07/2019 18/12/2019 19/12/2019 19/12/2019 17/01/2020 24/03/2020 24/03/2020	08/03/2019 0:00:00 28/03/2019 0:00:00 17/04/2019 0:00:00 05/04/2019 0:00:00 09/07/2019 0:00:00 18/12/2019 19/12/2019 0:00:00 08/01/2020 28/01/2020 9:31:00 06/04/2020 0:00:00 24/03/2020 0:00:00	ROUTINE RIGHT TO REPAIR 1 ROUTINE ROUTINE ROUTINE 22:00:00 EMERGENCY Urgent 2 day repair 13:30:00 ROUTINE RIGHT TO REPAIR 7 ROUTINE Urgent 2 day repair	G J G B J A E	glass. Fix flooring at w/m space and fit ply pad also Stain block over damp patch and emulsion livingroom ceiling following recurring roof leak (now repaired) no heating in property Fit UPVC overclad cills to all windows - replace defective cockspur handle on right hand window in livingroom - check all other handles. Further work req - replace PCB Confirmation : Fire Detection Upgrade carried outat AGS OOH call out - water ingress Out of Hours - General Building Craftsperson HR Water coming in through top of bedroom window. SURFACES:APPLY BACTDET AND HALOPHEN SM FAN:OVERHAUL DOMESTIC EXTRACT NO Supply 9 double glazed units - installation line to follow after COVID-19 restrictions are removed No CH/HW		gaskets are in place. Fix flooring at w/m space and fit ply pad also Stain block over damp patch and emulsion livingroom ceiling following recurring roof leak (now repaired) no heating in property Fit UPVC overclad cills to all windows - replace defective cockspur handl right hand window in livingroom - check all other handles. Further work req - replace PCB Confirmation : Fire Detection Upgrade carried out at AGS Confirmation call out - OOH Callout ORP20740 - water coming in through bedroom window from gutters Out of Hours - General Building Craftspei Water coming in through top of bedroom window. OOH call out engined reported that window needed to be resealed. Apply mould wash to bedroom walls - as per MD & MV Surfaces:Prepar wash down with RLT Bactdet solution prepare and apply one coat RL Halophen solution to walls or ceilings in accordance with manufacturers data sheet 2 coats of Biocheck matt. Fan:Overhaul any kind of domestic extractor fan dismantle and reasser clean and oil test and leave in working order. Supply 9 double glazed units - installation line to follow after COVID-19 restrictions are removed No CH/HW Meet GS engineer on Thursday 15th at 1pm to assisit in repair work No
AMES FREW LTD In Stewart Joiner and Glazier AMES FREW LTD AMES FREW LTD AMES FREW LTD IPS Housing Ltd Northern (Mitie)	184732 185914 186259 186277 188685 193584 193586	13/02/2019 28/03/2019 09/04/2019 28/03/2019 09/07/2019 18/12/2019 19/12/2019 19/12/2019 17/01/2020 24/03/2020	08/03/2019 0:00:00 28/03/2019 0:00:00 17/04/2019 0:00:00 05/04/2019 0:00:00 09/07/2019 0:00:00 18/12/2019 19/12/2019 0:00:00 08/01/2020 28/01/2020 9:31:00 06/04/2020 0:00:00	ROUTINE RIGHT TO REPAIR 1 ROUTINE ROUTINE ROUTINE 22:00:00 EMERGENCY Urgent 2 day repair 13:30:00 ROUTINE RIGHT TO REPAIR 7 ROUTINE	G J G B J A E	glass. Fix flooring at w/m space and fit ply pad also Stain block over damp patch and emulsion livingroom ceiling following recurring roof leak (now repaired) no heating in property Fit UPVC overclad cills to all windows - replace defective cockspur handle on right hand window in livingroom - check all other handles. Further work req - replace PCB Confirmation : Fire Detection Upgrade carried outat AGS OOH call out - water ingress Out of Hours - General Building Craftsperson HR Water coming in through top of bedroom window. SURFACES:APPLY BACTDET AND HALOPHEN SM FAN:OVERHAUL DOMESTIC EXTRACT NO Supply 9 double glazed units - installation line to follow after COVID-19 restrictions are removed		gaskets are in place. Fix flooring at w/m space and fit ply pad also Stain block over damp patch and emulsion livingroom ceiling following recurring roof leak (now repaired) no heating in property Fit UPVC overclad cills to all windows - replace defective cockspur handle right hand window in livingroom - check all other handles. Further work req - replace PCB Confirmation : Fire Detection Upgrade carried out at AGS Confirmation call out - OOH Callout ORP20740 - water coming in through bedroom window from gutters Out of Hours - General Building Craftsper Water coming in through top of bedroom window. OOH call out engineer reported that window needed to be resealed. Apply mould wash to bedroom walls - as per MD & MV Surfaces:Prepar wash down with RLT Bactdet solution prepare and apply one coat RL Halophen solution to walls or ceilings in accordance with manufacturers data sheet 2 coats of Biocheck matt. Fan:Overhaul any kind of domestic extractor fan dismantle and reassen clean and oil test and leave in working order. Supply 9 double glazed units - installation line to follow after COVID-19 restrictions are removed No CH/HW Meet GS engineer on Thursday 15th at 1pm to assisit in repair work Nor Working hours - General Building Craftsperson
In Stewart Joiner and Glazier AMES FREW LTD	184732 185914 186259 186277 188685 193584 193586 193597 194516 196454 196498	13/02/2019 28/03/2019 09/04/2019 28/03/2019 09/07/2019 18/12/2019 19/12/2019 19/12/2019 17/01/2020 24/03/2020 24/03/2020	08/03/2019 0:00:00 28/03/2019 0:00:00 17/04/2019 0:00:00 05/04/2019 0:00:00 09/07/2019 0:00:00 18/12/2019 19/12/2019 0:00:00 08/01/2020 28/01/2020 9:31:00 06/04/2020 0:00:00 24/03/2020 0:00:00	ROUTINE RIGHT TO REPAIR 1 ROUTINE ROUTINE ROUTINE 22:00:00 EMERGENCY Urgent 2 day repair 13:30:00 ROUTINE RIGHT TO REPAIR 7 ROUTINE Urgent 2 day repair	G J G B J A E	glass. Fix flooring at w/m space and fit ply pad also Stain block over damp patch and emulsion livingroom ceiling following recurring roof leak (now repaired) no heating in property Fit UPVC overclad cills to all windows - replace defective cockspur handle on right hand window in livingroom - check all other handles. Further work req - replace PCB Confirmation : Fire Detection Upgrade carried outat AGS OOH call out - water ingress Out of Hours - General Building Craftsperson HR Water coming in through top of bedroom window. SURFACES:APPLY BACTDET AND HALOPHEN SM FAN:OVERHAUL DOMESTIC EXTRACT NO Supply 9 double glazed units - installation line to follow after COVID-19 restrictions are removed No CH/HW Normal Working hours - General Building Craftspers		gaskets are in place. Fix flooring at w/m space and fit ply pad also Stain block over damp patch and emulsion livingroom ceiling following recurring roof leak (now repaired) no heating in property Fit UPVC overclad cills to all windows - replace defective cockspur handl right hand window in livingroom - check all other handles. Further work req - replace PCB Confirmation : Fire Detection Upgrade carried out at AGS Confirmation call out - OOH Callout ORP20740 - water coming in throug bedroom window from gutters Out of Hours - General Building Craftspe Water coming in through top of bedroom window. OOH call out enginer reported that window needed to be resealed. Apply mould wash to bedroom walls - as per MD & MV Surfaces:Prepar wash down with RLT Bactdet solution prepare and apply one coat RL Halophen solution to walls or ceilings in accordance with manufacturer data sheet 2 coats of Biocheck matt. Fan:Overhaul any kind of domestic extractor fan dismantle and reasser clean and oil test and leave in working order. Supply 9 double glazed units - installation line to follow after COVID-19 restrictions are removed No CH/HW Meet GS engineer on Thursday 15th at 1pm to assisit in repair work No Working hours - General Building Craftsperson EME - No signs of COVID Tenant has an appointment on 15th Oct for Joi
n Stewart Joiner and Glazier MES FREW LTD MES FREW LTD MES FREW LTD MES FREW LTD PS Housing Ltd Northern (Mitie) In Stewart Joiner and Glazier PS Housing Ltd Northern (Mitie) PS Housing Ltd Northern (Mitie) In Stewart Joiner and Glazier MES FREW LTD	184732 185914 186259 186277 188685 193584 193586 193597 194516 196454 196498	13/02/2019 28/03/2019 09/04/2019 28/03/2019 09/07/2019 18/12/2019 19/12/2019 19/12/2019 17/01/2020 24/03/2020 24/03/2020	08/03/2019 0:00:00 28/03/2019 0:00:00 17/04/2019 0:00:00 05/04/2019 0:00:00 09/07/2019 0:00:00 18/12/2019 19/12/2019 0:00:00 08/01/2020 28/01/2020 9:31:00 06/04/2020 0:00:00 24/03/2020 0:00:00	ROUTINE RIGHT TO REPAIR 1 ROUTINE ROUTINE ROUTINE 22:00:00 EMERGENCY Urgent 2 day repair 13:30:00 ROUTINE RIGHT TO REPAIR 7 ROUTINE Urgent 2 day repair	G J G B J A E	glass. Fix flooring at w/m space and fit ply pad also Stain block over damp patch and emulsion livingroom ceiling following recurring roof leak (now repaired) no heating in property Fit UPVC overclad cills to all windows - replace defective cockspur handle on right hand window in livingroom - check all other handles. Further work req - replace PCB Confirmation : Fire Detection Upgrade carried outat AGS OOH call out - water ingress Out of Hours - General Building Craftsperson HR Water coming in through top of bedroom window. SURFACES:APPLY BACTDET AND HALOPHEN SM FAN:OVERHAUL DOMESTIC EXTRACT NO Supply 9 double glazed units - installation line to follow after COVID-19 restrictions are removed No CH/HW		gaskets are in place. Fix flooring at w/m space and fit ply pad also Stain block over damp patch and emulsion livingroom ceiling following recurring roof leak (now repaired) no heating in property Fit UPVC overclad cills to all windows - replace defective cockspur handl right hand window in livingroom - check all other handles. Further work req - replace PCB Confirmation : Fire Detection Upgrade carried out at AGS Confirmation call out - OOH Callout ORP20740 - water coming in throug bedroom window from gutters Out of Hours - General Building Craftspe Water coming in through top of bedroom window. OOH call out enginer reported that window needed to be resealed. Apply mould wash to bedroom walls - as per MD & MV Surfaces:Prepar wash down with RLT Bactdet solution prepare and apply one coat RL Halophen solution to walls or ceilings in accordance with manufacturer data sheet 2 coats of Biocheck matt. Fan:Overhaul any kind of domestic extractor fan dismantle and reasser clean and oil test and leave in working order. Supply 9 double glazed units - installation line to follow after COVID-19 restrictions are removed No CH/HW Meet GS engineer on Thursday 15th at 1pm to assisit in repair work No Working hours - General Building Craftsperson EME - No signs of COVID Tenant has an appointment on 15th Oct for Joi
In Stewart Joiner and Glazier AMES FREW LTD	184732 185914 186259 186277 188685 193584 193586 193597 194516 196454 196498	13/02/2019 28/03/2019 09/04/2019 28/03/2019 09/07/2019 18/12/2019 19/12/2019 19/12/2019 17/01/2020 24/03/2020 24/03/2020	08/03/2019 0:00:00 28/03/2019 0:00:00 17/04/2019 0:00:00 05/04/2019 0:00:00 09/07/2019 0:00:00 18/12/2019 19/12/2019 0:00:00 08/01/2020 28/01/2020 9:31:00 06/04/2020 0:00:00 24/03/2020 0:00:00	ROUTINE RIGHT TO REPAIR 1 ROUTINE ROUTINE ROUTINE 22:00:00 EMERGENCY Urgent 2 day repair 13:30:00 ROUTINE RIGHT TO REPAIR 7 ROUTINE Urgent 2 day repair	G J G B J A E	glass. Fix flooring at w/m space and fit ply pad also Stain block over damp patch and emulsion livingroom ceiling following recurring roof leak (now repaired) no heating in property Fit UPVC overclad cills to all windows - replace defective cockspur handle on right hand window in livingroom - check all other handles. Further work req - replace PCB Confirmation : Fire Detection Upgrade carried outat AGS OOH call out - water ingress Out of Hours - General Building Craftsperson HR Water coming in through top of bedroom window. SURFACES:APPLY BACTDET AND HALOPHEN SM FAN:OVERHAUL DOMESTIC EXTRACT NO Supply 9 double glazed units - installation line to follow after COVID-19 restrictions are removed No CH/HW Normal Working hours - General Building Craftspers		gaskets are in place. Fix flooring at w/m space and fit ply pad also Stain block over damp patch and emulsion livingroom ceiling following recurring roof leak (now repaired) no heating in property Fit UPVC overclad cills to all windows - replace defective cockspur handle right hand window in livingroom - check all other handles. Further work req - replace PCB Confirmation : Fire Detection Upgrade carried out at AGS Confirmation call out - OOH Callout ORP20740 - water coming in through bedroom window from gutters Out of Hours - General Building Craftsper Water coming in through top of bedroom window. OOH call out enginee reported that window needed to be resealed. Apply mould wash to bedroom walls - as per MD & MV Surfaces:Prepare wash down with RLT Bactdet solution prepare and apply one coat RLT Halophen solution to walls or ceilings in accordance with manufacturers data sheet 2 coats of Biocheck matt. Fan:Overhaul any kind of domestic extractor fan dismantle and reassen clean and oil test and leave in working order. Supply 9 double glazed units - installation line to follow after COVID-19 restrictions are removed No CH/HW Meet GS engineer on Thursday 15th at 1pm to assisit in repair work Nor Working hours - General Building Craftsperson EME - No signs of COVID Tenant has an appointment on 15th Oct for Joir and Gas Sure to attend but she has no ch/hw again. Topping up the press
n Stewart Joiner and Glazier MES FREW LTD MES FREW LTD MES FREW LTD MES Housing Ltd Northern (Mitie) In Stewart Joiner and Glazier MES Housing Ltd Northern (Mitie) IPS Housing Ltd Northern (Mitie) I	184732 185914 186259 186277 188685 193584 193586 193597 194516 196454 196498	13/02/2019 28/03/2019 09/04/2019 28/03/2019 09/07/2019 18/12/2019 19/12/2019 19/12/2019 17/01/2020 24/03/2020 24/03/2020 13/10/2020	08/03/2019 0:00:00 28/03/2019 0:00:00 17/04/2019 0:00:00 05/04/2019 0:00:00 09/07/2019 0:00:00 18/12/2019 19/12/2019 0:00:00 08/01/2020 28/01/2020 9:31:00 06/04/2020 0:00:00 24/03/2020 0:00:00	ROUTINE RIGHT TO REPAIR 1 ROUTINE ROUTINE ROUTINE 22:00:00 EMERGENCY Urgent 2 day repair 13:30:00 ROUTINE RIGHT TO REPAIR 7 ROUTINE Urgent 2 day repair	G J G B J A E	glass. Fix flooring at w/m space and fit ply pad also Stain block over damp patch and emulsion livingroom ceiling following recurring roof leak (now repaired) no heating in property Fit UPVC overclad cills to all windows - replace defective cockspur handle on right hand window in livingroom - check all other handles. Further work req - replace PCB Confirmation: Fire Detection Upgrade carried outat AGS OOH call out - water ingress Out of Hours - General Building Craftsperson HR Water coming in through top of bedroom window. SURFACES:APPLY BACTDET AND HALOPHEN SM FAN:OVERHAUL DOMESTIC EXTRACT NO Supply 9 double glazed units - installation line to follow after COVID-19 restrictions are removed No CH/HW Normal Working hours - General Building Craftspers EME - No signs of COVID Tenant has an appointment on 15th Oct for Joiner and Gas Sure		gaskets are in place. Fix flooring at w/m space and fit ply pad also Stain block over damp patch and emulsion livingroom ceiling following recurring roof leak (now repaired) no heating in property Fit UPVC overclad cills to all windows - replace defective cockspur handl right hand window in livingroom - check all other handles. Further work req - replace PCB Confirmation: Fire Detection Upgrade carried out at AGS Confirmation call out - OOH Callout ORP20740 - water coming in through bedroom window from gutters Out of Hours - General Building Craftsper Water coming in through top of bedroom window. OOH call out engineer reported that window needed to be resealed. Apply mould wash to bedroom walls - as per MD & MV Surfaces:Prepar wash down with RLT Bactdet solution prepare and apply one coat RL Halophen solution to walls or ceilings in accordance with manufacturers data sheet 2 coats of Biocheck matt. Fan:Overhaul any kind of domestic extractor fan dismantle and reasser clean and oil test and leave in working order. Supply 9 double glazed units - installation line to follow after COVID-19 restrictions are removed No CH/HW Meet GS engineer on Thursday 15th at 1pm to assisit in repair work Not Working hours - General Building Craftsperson EME - No signs of COVID Tenant has an appointment on 15th Oct for Join and Gas Sure to attend but she has no ch/hw again. Topping up the pres
n Stewart Joiner and Glazier MES FREW LTD IPS Housing Ltd Northern (Mitie)	184732 185914 186259 186277 188685 193584 193586 193597 194516 196454 196498	13/02/2019 28/03/2019 09/04/2019 28/03/2019 09/07/2019 18/12/2019 19/12/2019 19/12/2019 17/01/2020 24/03/2020 24/03/2020	08/03/2019 0:00:00 28/03/2019 0:00:00 17/04/2019 0:00:00 05/04/2019 0:00:00 09/07/2019 0:00:00 18/12/2019 19/12/2019 0:00:00 08/01/2020 28/01/2020 9:31:00 06/04/2020 0:00:00 24/03/2020 0:00:00	ROUTINE RIGHT TO REPAIR 1 ROUTINE ROUTINE ROUTINE 22:00:00 EMERGENCY Urgent 2 day repair 13:30:00 ROUTINE RIGHT TO REPAIR 7 ROUTINE Urgent 2 day repair	G J G B J A E J G	glass. Fix flooring at w/m space and fit ply pad also Stain block over damp patch and emulsion livingroom ceiling following recurring roof leak (now repaired) no heating in property Fit UPVC overclad cills to all windows - replace defective cockspur handle on right hand window in livingroom - check all other handles. Further work req - replace PCB Confirmation : Fire Detection Upgrade carried outat AGS OOH call out - water ingress Out of Hours - General Building Craftsperson HR Water coming in through top of bedroom window. SURFACES:APPLY BACTDET AND HALOPHEN SM FAN:OVERHAUL DOMESTIC EXTRACT NO Supply 9 double glazed units - installation line to follow after COVID-19 restrictions are removed No CH/HW Normal Working hours - General Building Craftspers EME - No signs of COVID Tenant has an appointment on 15th Oct for Joiner and Gas Sure to attend but xxx has no ch/hw again. Topping up the pressure isnt working now please		gaskets are in place. Fix flooring at w/m space and fit ply pad also Stain block over damp patch and emulsion livingroom ceiling following recurring roof leak (now repaired) no heating in property Fit UPVC overclad cills to all windows - replace defective cockspur handle right hand window in livingroom - check all other handles. Further work req - replace PCB Confirmation: Fire Detection Upgrade carried out at AGS Confirmation call out - OOH Callout ORP20740 - water coming in through bedroom window from gutters Out of Hours - General Building Craftsper Water coming in through top of bedroom window. OOH call out enginee reported that window needed to be resealed. Apply mould wash to bedroom walls - as per MD & MV Surfaces:Prepare wash down with RLT Bactdet solution prepare and apply one coat RLT Halophen solution to walls or ceilings in accordance with manufacturers data sheet 2 coats of Biocheck matt. Fan:Overhaul any kind of domestic extractor fan dismantle and reassen clean and oil test and leave in working order. Supply 9 double glazed units - installation line to follow after COVID-19 restrictions are removed No CH/HW Meet GS engineer on Thursday 15th at 1pm to assisit in repair work Nor Working hours - General Building Craftsperson EME - No signs of COVID Tenant has an appointment on 15th Oct for Join and Gas Sure to attend but she has no ch/hw again. Topping up the press isnt working now please attend to carry out temp repair if unable to do s

The tenant has had on going dampness or condensation in xxx home works have been previously carried out but the problem persists. Please attend and carry out a survey of the water ingress cause and recommendations to rectify and whether or not the internal issues are caused by external or internal reasons

LATTO MAINTENANCE 200340 27/10/2020 0:00:00 ROUTINE S Carry out independent review of water ingress or condensation causes and compile report